































2014 Porsche Cayenne
















2014 Porsche Cayenne







Summary

Poor

Exterior

Wiper Blades - Needs replacement

Body Panels - Poor quality repairs

Right Rear Fender - Panel repaired, body filler used

Right Rear Door and frame - Panel repaired majority of door covered in body filler

Door refitted

Right Front Fender - Panel repaired majority of door covered in body filler

Right Front Door and frame - Panel repaired majority of door covered in body filler

Door refitted

Trim pieces and badges - Front porch about Paylink

Paint - Visible difference in colours

Heavy cracking of body filler

Exhaust tips - Driver-side exhaust tip damaged

Tires

Wheels - Heavy damage to rims

Underbody

Ball Joints/Bushings - Control arm bushings and ball joints cracked

Underhood

Power Steering Fluid - Below minimum